

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 5 77 WEST JACKSON BOULEVARD CHICAGO, ILLINOIS 60604

DATE:

1111 1 7 2018

SUBJECT:

CLEAN AIR ACT INSPECTION REPORT

Al-Corn Clean Fuel

FROM:

Gregory Gehrig, Environmental Engineer

AECAB (MI/WI)

THRU:

Sarah Marshall, Section Chief

AECAB (MI/WI)

TO:

File

BASIC INFORMATION

Facility Name: Al-Corn Clean Fuel

Facility Location: 797 5th St., Claremont, MN

Date of Inspection: June 29, 2018

Lead Inspector: Gregory Gehrig, Environmental Engineer

Other Attendees: From Al-Corn Clean Fuel: Randall J. Doyal, C.E.O; J.P. Parenteau, Plant

Manager; Thomas Harwood, Owner's Representative; Henry Blair, Safety & Training

Compliance Manager.

Contact Email: rdoyal@al-corn.com.

Purpose of Inspection: CAA Compliance

Facility Type: Ethanol production from corn

Regulations Central to Inspection: SIP, NSPS and MACT

Arrival Time: 0800 hrs **Departure Time:** 1015 hrs

Facility Name: Al-Corn Clean Fuel

Facility Location: 797 5th St., Claremont, MN

Date of Inspection: June 29, 2018

Inspection Type:

☑ Unannounced Inspection☑ Announced Inspection

OPENING CONFERENCE

☐ CBI warning to facility provided

The following information was obtained verbally from facility personnel.

Company Ownership: No recent ownership change.

Process Description:

Al-Corn Clean Fuel (Al-Corn) is permitted to produce 130 million gallons per year of ethanol from corn based on their permit issued March 3, 2017, although they are still in the process of expanding their facility to that capacity. They also produce distillers dried grains (DDGS). They have ten fermenters, one beer well and one associated scrubber for pollution control. Al-Corn uses one recuperative thermal oxidizer (TO) and a new regenerative thermal oxidizer (RTO) to control emissions from the mash drying operations conducted to produce DDGS. They load out denatured ethanol via both rail and tank wagon, although mostly by rail.

TOUR INFORMATION

EPA toured the facility: Yes

Data Collected and Observations:

FLIR video was taken of VOC emission points and possible VOC emission points. Al-Corn was operating normally during the facility tour. The following was observed during the tour:

- Control room, where pollution control readings were collected.
- The grain offloading baghouse was at 1.0 inch of water pressure differential.
- Scrubber, which was operating at a pressure differential of 16.9 inches of water, a flow of 145 gallon per minute of water, and additive flow rate of 20 milliliters per minute.
- Fermentors and beer well. No issues noted on newer fermenters. One leaking fabric-type temporary connector on older fermentor #5.
- Older distillation/molecular sieves.
- RTO, which was operating at 1,648 °F.
- TO, which was operating at 1,480 °F.
- Ethanol truck loadout, with leak noted at gasket on vapor return hose.

Field Measurements: were not taken during this inspection.

Facility Name: Al-Corn Clean Fuel

Facility Location: 797 5th St., Claremont, MN

Date of Inspection: June 29, 2018

RECORDS REVIEW

- Monthly LDAR report conducted June 19, 2018 (taken)
- Facility diagram (taken)

CLOSING CONFERENCE

Requested documents:

None

Compliance Assistance: EPA indicated that Al-Corn should fully investigate and mitigate uncontrolled venting from the truck loadout and the fermentator #5 fabric-type connector. At the closing conference, Al-Corn personnel indicated they were initiating action to address these concerns.

Concerns: None

SIGNATURES

Lead Inspector:

Section Chief:

Facility Name: Al-Corn Clean Fuel Facility Location: 797 5th St., Claremont, MN Date of Inspection: June 29, 2018

APPENDIX A: DIGITAL IMAGE LOG

1. Inspector Name:	2. Date(s) of Inspection:
Gregory Gehrig	June 29, 2018
3. Company/Facility Name:	4. Street Address, City, State:
Al-Corn Clean Fuel	797 5th St., Claremont, MN
5. Number of Images:	6. Archival Record Location:
5	CD-R labeled Al-Corn Images 6.29.2018

Image name	Date and Time (CDT)	Description
MOV_2185	June 29, 2018 at 0837	FLIR video of ethanol loadout operation, including the
		flare. Leak noted at vapor return line fitting.
MOV_2186	June 29, 2018 at 0840	FLIR video of TO and RTO.
MOV 2187	June 29, 2018 at 0914	FLIR video of scrubber outlet and components atop beer
_		well and newer fermentors.
MOV 2188	June 29, 2018 at 0926	FLIR video of components on older fermenters. Venting
		from fabric-type connector on Ferm #5.
MOV_2189	June 29, 2018 at 0947	FLIR video of older fermenters.